



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 29, 2013

Reviewed: 

Mine Name: Lucero Red	Permit Number: S/055/0023
Operator Name: Quality Building Stone	Inspection Date: 05/22/2013
Inspector(s): Wayne Western	Time:
Other Participants: none	Mine Status: Act
Weather Condition: 70's clear skies	Last Inspection: April 20, 2011
Bond Renewal Date: 1/12/2009	Bond Amount: \$22,000.00
Surface Ownership: Fee	Mineral Ownership: Fee
Last Year of Production: 2011	Acreage:

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond needs to be escalated.

The permit fees need to be paid for 2013


The site was environmentally sound.

Conclusions and Recommendations:

The Division should follow up on the bond and permit fees.

Directions to Site:

Inspector's Signature

A handwritten signature in black ink, appearing to read "Wayne Lucero", is written over a horizontal line.

WHW:

cc: (OPERATOR)

O:\M055-Wayne\S0550023-LuceroRed\inspections\Insp-050222013.doc